KNOTS 2U, LTD. LUGGAGE DOOR STRUT KIT

INSTALLATION MANUAL ISSUE DATE 01/01/98

APPLICABLE MODELS:


BEECHCRAFT MODELS: B95A, D95A, E95, 95-55, 95-A55, 95-B55A, 95-B55B, 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC WITH EXTENDED LUGGAGE DOOR

KNOTS 2U, LTD. 709 AIRPORT ROAD BURLINGTON, WI 53105 262.763.5100 www.knots2u.com

Rev#	Date	Page (s)	Effect
Α	03/17/03	ALL	Added an additional attachment screw to attach
			Part No. SILBKT. Clean-up of manual.

TABLE OF CONTENTS

<u>SEC</u>	TION No.	PAGE No.
1.0	-DETAIL 1	1
2.0	-PARTS LIST-	2
3.0	-PAPERWORK-	2
4.0	-MAINTENANCE MANUAL	2
5.0	-SUPPLEMENTAL TYPE CERTIFICATE	3



INSTALLING P/N SILBKT AND P/N DRBKT

- 1. REMOVE INTERIOR ABOVE LUGGAGE DOOR OPENING. LOCATE P/N SILBKT IN SHOWN POSITION. IF PART FALLS ON AN EXISTING RIVET, THE RIVET MAY BE DRILLED OUT AND REPLACED WITH A COUNTERSUNK RIVET. DRILL (3) #27 HOLES AND RIVET P/N SILBKT IN PLACE USING (3) CR3242-4-2 CHERRY MAX RIVETS. INTERIOR MAY BE RE-INSTALLED.
- 2. LOCATE P/N DRBKT IN LOCATION SHOWN ABOVE. IF PART FALLS ON AN EXISTING RIVET, THE RIVET MAY BE DRILLED OUT AND REPLACED WITH A COUNTERSUNK RIVET. BEFORE DRILLING MOUNTING HOLES, CLOSE DOOR AND CONFIRM MEASURMENT OF 11.50" BETWEEN CENTER OF P/N DRBKT AND CENTER OF P/N SILBKT. DRILL (2) #27 HOLES AND RIVET P/N SILBKT IN PLACE USING (2) CR3242-4-2 CHERRY MAX RIVETS. 3. STRUT MAY BE INSTALLED PER DIAGRAM.
- 4. EXISTING CHAIN AND ATTACHMENTS MAY BE REMOVED AND THE HOLES FILLED WITH RIVETS.

PAGE -1-



-SECTION 2.0 PARTS LIST-

<u>PART No.</u>	<u>No. REQ.</u>	<u>DESCRIPTION</u>
STRUT3	1	17" (20psi) Pneumatic Strut
SILBKT	1	Sill Bracket
DRBKT	1	Door Bracket
CR3242-4-3	5	Cherry Max Rivet

-SECTION 3.0 PAPERWORK-

Perform paperwork (337 and logbook entries). Place Supplemental Type Certificate and KNOTS 2U, LTD. MAINTENANCE MANUAL with log books.

Weight and balance change = Negligible

-SECTION 4.0 MAINTENANCE MANUAL-KNOTS 2U, LTD.

BEECHCRAFT MODELS 55 / 56 WITH EXTENDED LUGGAGE DOOR LUGGAGE DOOR STRUT

PART A. INSPECTION.

1. During annual or 100 hour inspections, inspect attachment hardware and confirm strut pressure is sufficient to retain luggage door in open position.

PART B. MAINTENANCE.

- 1. If attachment hardware is found to be excessively worn or loose during the 100 hour/annual inspection, it should be replaced.
- 2. If the strut pressure is insufficient to hold door in an open position, it should be replaced.

PART C. CRACKING OR DEFECTS.

1. If a crack is found in the door area where brackets are attached, repair the crack according to FAR 43.13 1A, Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair, Chapter 2.

Page -2-

FAA APPROVED MODEL LIST (AML) NO. SAU0899CH KNOTS 2U, LTD. FOR

INSTALLING PNEUMATIC STRUT

ISSUE DATE: 6/24/98

ITEM	AIRCRAFT AIRCRAFT		ORIGINAL TYPE	CERTIFICATION BASIS	INSTALLATION INSTRUCTIONS		AFM	AML
	MAKE	MODEL	CERTIFICATE	FOR		REVISION	SUPPLEMENT	AMENDMENT
			Number	ALTERATION	number	NO. & DATE	NUMBER/DATE	DATE
1	Raytheon Aircraft Company (Beech)	35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A,	3 A 15	CAR 3	Beechcraft Models 33/35 "Knots 2U, Ltd. Luggage Door Strut Installation Manual"	1/1/98	N/A	N/A
2	Raytheon Aircraft Company (Beech)	95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC	3A16	CAR 3	Beechcraft Models 55/56 "Knots 2U, Ltd. Luggage Door Strut lnstallation Manual"	1/1/98	N/A	N/A

FAA APPROVED:

Gregory J. Michalik, Senior Aerospace Engineer

Airframe & Administrative Branch

Chicago Aircraft Certification Office

Reissued: <u>7/8/98</u>